

## S.C.B. Engineering Co., Ltd.



**Corroded reinforcement** behind spalling concrete



Remove rust on reinforcement steel



Column prepared and new reinforcement fixed for re - casting repair



Two coats of **Anti-Rust Protection** 



**Application of Epoxy Bonding Agent** 



**Completed repairs** 



**Setting form work** 



**Repair with Non-shrink Grout** 

**Concrete Restoration** 

PROJECT : Prince of Songkla University (Pattani Campus)